Stray Voltage Investigation by Vitatech Electromagnetics, LLC

Sponsored by

National Regulatory Research Institute (NRRI) www.nrri.ohio-state.edu The Ohio State University Columbus, Ohio Ray Lawton, Director Robert Burns, Electric Research

Initial Meeting & Information 9 October 2002

- JCP&L provided project history & test info – Initial Stray Voltage compliant 22 July 2002
 - Standard troubleshooting/fixed some problems
 - Implement vigorous program to fix problem
 - Reconductored Driscoll neutrals: 10 V to 5 V
 - Installed new ground rods & down grounds
 - NJ State geological survey high resistivity soil
 - test showed reduction in load lowers NEV
 - JCP&L offered full cooperation and access to Vitatech

Perceived Stray Voltage Events & Causes

In July 2002 during the peak summer load and *exceptional drought* conditions several JCP& L customers adjacent to the Herbertsville Substation on Driscol and Frede Drives in the Town of Brick, New Jersey, reported tingling sensations known as stray voltage while touching their pools, Jacuzzis, outdoor showers and other conductive objects. Testing revealed the problem still persisted with the main electrical panels de-energized (breakers or fuses open) indicating the stray currents (the cause of stray voltages) appeared to enter each residence from the utility pole via the overhead secondary service neutral conductor, which is bonded to the neutral-ground bus in each main electrical panel. Also grounded to the neutral-ground bus are the metallic water service pipe, ground rod, CATV and telephone drops (see diagram below for pictorial representation).



Ground Currents Caused by Residential Loads in a Typical Situation



Perceived Stray Voltage Events & Causes

On the utility poles the overhead secondary service neutrals are bonded to the primary neutrals, down-grounds and ground rods, CATV and telephone cable guy wires. Under normal seasonal conditions with ample rain and low soil resistivity, the primary neutral currents (known as zero-sequence currents because of the unbalanced phasing) return to the substation via the overhead primary neutral conductors and underground earth channels (composed of conductive layers of soil). Normally, earth channels return a significant portion of the primary neutral currents, which enter the underground earth channels from the pole down-ground rods, and metallic water service laterals/mains that meander under the front yards, sidewalks and streets.

The Herbertsville substation and adjacent neighborhoods "showed uniform geology in the area of concern....fine to coarse quartz sand with quartz-pebble" according to the NJGS. Since sandy soil normally has high resistivity, during the 2002 drought, the existing earth channels quickly disappeared as the water table (saturation zone) retreated forcing significantly more primary neutral current to return to the substation via the overhead primary neutrals. This additional primary return current increased the voltage potential (difference) between the substation ground (now electrically isolated from the adjacent neighborhoods due to the exceptional drought and sandy conditions) and the multi-grounded primary neutral (MGN) distribution systems in the adjacent neighborhoods. The consequence was an increase in neutral-to-earth voltages (NEV) on the pole down-grounds and grounded-neutrals in the main electrical panels within homes near and adjacent to the Herbertsville substation.

Herbertsville Substation

- Two 34.5 kV sub-transmission lines
- 25 MVA Transformer Bank #1 Circuits 82 & 83
- 20 MVA Transformer Bank #2 Circuits 80 & 81
- Upgraded Circuits 82 & 83 from 4.8 kV delta
- Primary Feeder Sizes: 397AA
- Neutral Feeder Sizes: Mix #2 ACSR and #2/0 AA
- Bank #2 Added 500 MCM Neutral From X0 bushing to Switchgear Neutral – No change in NEV



Figure #1, Herbertsville Substation Single Line Diagram





Herbertsville Substation Looking Eastward Circuit 83 & 34.5 kV













Rec 1 File NJ SUB1 Taken 10/9/2 ID-HERB SUB PG PEAK = 72.1 mG, MEAN = 9.19 mG, STD = 8.51 mG, MEDIAN = 7.44 mG

Figure #7 Herbertsville Substation Magnetic Flux Density Data Perimeter Hatch & Contour Plots At Ground & 1-meter Levels

PEAK = 71.3 mG, MEAN = 8.15 mG, STD = 8.01 mG, MEDIAN = 6.28 mG



Contour (Mapped) Hatch & Image Plots At Ground Level

(BrinmG) Hatch Plot X in feet West Ο Start -20 ð West 20-Ö Start VitaTech Engineering, LLC November 2, 2002





Figure #11 - Magnetic Flux Density Data Oak Knoll Dr. & Taft Ave., October 17, 2002

Hatch & Profile Plots Recorded at Ground Level



Profile Plot

3-D Plot

500











Vitatech's Final Assessment

- Primary neutrals on Lines 80, 81, 82 and 83 not sized to accommodate soil and \bullet exceptional Summer 2002 drought conditions.
- Poor soil conditions and low water table (saturation zone) at the Herbertsville lacksquaresubstation and four distribution areas – impedes earth return currents traveling back to substation. Soil resistivity increased by a factor of 2-3 during the summer of 2002 drought: soil resistivity during normal summers with adequate rain probably ranged from 600 – 1200 ohm-meters, then increased to 2,000 to 3,000 ohm-meters, if not higher, during drought.
- Unbalanced phases exceeding 10% on Lines 80, 81, 82 and 83 during average load ${}^{\bullet}$ conditions -- could approach 20-25% during summer peak loads.

Vitatech's Recommendations

- Oversize primary neutrals on Lines 80, 81, 82 and 83 as specified in Figure #12, Recommended ulletUpgrade To Primary Neutrals to match the size and impedance of the 397AA phase conductors. A total of 37,600 feet (7.12 miles) of upgraded 397AA primary neutrals are recommended to mitigate the stray voltage problem and achieve a neutral-to-earth voltage of 4-5 volts during summer months on the substation grid and down-grounds of the adjacent neighborhoods during peak summer loads. Specific routes and circuit length details for the recommended upgraded primary neutrals are provided in Figure #12; however, selected lateral circuits may also require upgraded 397AA neutrals to achieve the 4-5 volt summer performance objective including: Azalea Drive, Truman Drive, Harding Drive, Roosevelt Drive and Old Squan Drive.
- No additional ground rods, mats or plates are recommended for the substation ground grid; however, the substation ground plane should be expanded to the extents of the new fence line with additional grounds bonded from the grid to the fence, where needed. (Note: this will have no adverse effect on stray voltage.)
- Balance the phases on Lines 80, 81, 82 and 83 to within 10% (as measured by the SCADA) ۲ equipment at the substation) during average loads (20-25%) and no more than 15% during peak summer loads to minimize zero-sequence currents.

Vitatech's Recommendations

Returning earth currents are migrating up the down-grounds and raising the Neutral- ${}^{\bullet}$ to-Earth Voltage (NEV) and the Earth-to-Earth voltage in the neighborhood adjacent to the substation. Remember, the primary neutral return current is a sum of the harmonic (3rd,5th, 7th, 9th, 11th, 13th, 15th, etc.) components, especially the triplen harmonics, which are due to the zero-sequence currents of the unbalanced phases.

Therefore, decreasing the harmonic content on the primary neutrals (not an easy task) will concurrently reduce the neutral-to-earth voltage (NEV) on the down-grounds, substation grid and earth-to-earth voltages around the substation and adjacent neighborhood. EPRI verified Vitatech recommendations were correct and designed harmonic filters for the distribution lines which lowered the NEV to less than 3 V.